







Assembly Instructions



2103






60 min







2103

1	1	1600x400x18MM
2	1	1600x400x18MM
3A	1	398x264x18MM
3B	1	398x264x18MM
4	1	380x264x18MM
5	2	770x357x15MM
6	1	1572x274x5MM
7A	1	383x260x18MM
7B	1	383x260x18MM









 φ 15x12 Ax12	 M6x35 Bx12	 φ 8x40 Cx12	 M3.5x15 Dx34
 Ex8	 M6x55 Fx4	 M6 Gx12	 φ15xM6x1 Hx16
 Ix4	 Jx8	 M6x15 Kx12	 5# Lx1
 φ38x190 Mx4	 70x70x20 Nx4	 Ox2	 Px1
 Qx2	 Rx2		




1





2



3




4




5



Ax6





6





8-12



7




8



9-12

9




1



DX8





IX4




10-12

1 1




1 2



11-12

13



12-12